

VEHICLE INSPECTION REPORT

YV68MWM

Ford Transit Connect 200 1.5 ECOBLUE 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 14/02/2019

Year 2019

Mileage 122,249 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXWPGRJR10970

Body Style Panel Van L1

MOT Due 13/02/2026

CAP Clean £4,225.00

CAP Average £3,700.00

CAP Below £2,975.00

Gearbox MANUAL

Gears 6

FLYWHEEL KNOCKING SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door Mirror Assy nsf
Broken
Replace



3: Door nsr
 Scratched
 UpTo 25mm Not Thru Paint



4: Qtr Panel nsr
 Scratched
 Over 25mm Not Thru Paint



5: Door osr
 Dented
 With Paint Damage



6: Bumper Rear
 Scratched
 Over 25mm Not Thru Paint



7: Door Mirror Assy osf
 Scuffed (Unpainted)
 UpTo 100mm



8: Other
 N/A
 N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK