

VEHICLE INSPECTION REPORT

PE63NHD

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	18/10/2013	VIN	ZLRAE45FF0L431540	Cab Type	DAY CAB
Year	2013	Body Style	Box Van	Gearbox	MANUAL
Mileage	813,595 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	30/04/2026	Tail Lift	Cantilever

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Panel Front
Cracked
Replace

2: Door osf
Scratched
Over 25mm Thru Paint



3: Door osf
Dented
With Paint Damage

4: Door osf
Chipped
Multiple Chips



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Bumper Front
Scratched
Over 100mm Thru Paint





9: Carpets Front
 Holed
 Over 3mm

10: Door Pad osf
 Soiled
 Heavy

Interior

Carpet Condition	Poor		Upholstery Condition	Poor
Seat Condition	OK		Odour	-
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			