

VEHICLE INSPECTION REPORT

NU69XTN

Ford Transit Connect 200 1.5 EcoBlue 75ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/12/2019

Year 2019

Mileage 28,984 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXWPGRKU82706

Body Style Panel Van L1

MOT Due 16/12/2025

CAP Clean £6,025.00

CAP Average £5,275.00

CAP Below £4,200.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, TOW BAR, AD-BLUE

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Chipped
Multiple Chips



3: Qtr Panel osr
Dented
Over 30mm



4: Roof
Dented
Over 30mm



5: Door osf
Chipped
Multiple Chips



6: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		