

VEHICLE INSPECTION REPORT

BT15TMY

Iveco Daily 70-170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 15/06/2015

Fuel Type Diesel

Body Style Panel Van

Year 2015

Colour WHITE

Gearbox MANUAL

Mileage 119,612 Km TBC

VIN ZCFC270C505011968

WARNING LIGHTS ON DASH TOW BAR, SIDE LOAD DOOR


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
Over 10mm



3: Bumper Front
Cracked
Over 25mm



4: Bumper Front
Chipped
Over 5mm



5: Moulding nsf Wing
Scuffed (Unpainted)
Over 100mm



6: Wing nsf
Dented
With Paint Damage




7: Door nsf
Scratched
UpTo 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint





9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint

10: Qtr Panel nsr
Rusted
Over 5mm



11: Panel Rear
Scratched
Rusted

12: Bumper Front Moulding
Broken
Replace



13: Door nsr
Rusted
Over 5mm

14: Door osr
Rusted
Over 5mm



15: Panel Rear
Dented
With Paint Damage

16: Panel Rear
Scratched
Rusted



17: Qtr Panel osr
Chipped
Over 5mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK		
ABS light illuminated	OK		